

SumBe..F	45.2	0.2	29 Cu	<	51 Sb	<		
11 Na	54.24	0.02	30 Zn	<	52 Te	<		
12 Mg	<		31 Ga	<	53 I	<		
13 Al	<		32 Ge	<	55 Cs	<		
14 Si	<		33 As	<	56 Ba	<		
15 P	<		34 Se	<	SumLa..Lu	0.04	0.13	
16 S	<		35 Br	<	72 Hf	<		
16 So	0.31	0.03	37 Rb	<	73 Ta	<		
17 Cl	0.13	0.01	38 Sr	<	74 W	<		
18 Ar	<		39 Y	<	75 Re	<		
19 K	0.010	0.001	40 Zr	<	76 Os	<		
20 Ca	<		41 Nb	<	77 Ir	<		
21 Sc	<		42 Mo	<	78 Pt	<		
22 Ti	<		44 Ru	<	79 Au	<		
23 V	<		45 Rh	<	80 Hg	<		
24 Cr	<		46 Pd	<	81 Tl	<		
25 Mn	<		47 Ag	<	82 Pb	<		
26 Fe	0.11	0.01	48 Cd	<	83 Bi	<		
27 Co	<		49 In	<	90 Th	<		
28 Ni	<		50 Sn	<	92 U	<		

==== Light Elements =====

==== Noble Elements =====

==== Lanthanides =====

4 Be
5 B
6 C
7 N
8 O
9 F

45.2 0.2

44 Ru <
45 Rh <
46 Pd <
47 Ag <
75 Re <
76 Os <
77 Ir <
78 Pt <
79 Au <

57 La <
58 Ce <
59 Pr <
60 Nd <
62 Sm <
63 Eu <
64 Gd <
65 Tb <
66 Dy <
67 Ho <
68 Er <
69 Tm <
70 Yb <
71 Lu <